



- 1. WOULD LIKE AN EXPLANATION OF (1) WHY, IF THE FAILURE OCCURRED ON 6-3-64 WE WERE NOT INFORMED UNTIL 6-9-64 IN A ROUTINE MESSAGE AND (2) WHY IS CURRENT APPLIED THROUGH A NEWLY WIRED JUNCTION BOX DIRECTLY TO YOUR EXPENSIVE AND DELICATE PACKAGE WITHOUT A ROUTINE CIRCUIT VERIFICATION?
 - 2. PLS SUBSTITUTE F SYSTEM FOR E IN DELIVERY SCHEDULE.





EPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COM NO.

Approved For Release 2002/06/11: CIA-RDP67B00820R000400040008-0